

Jan 3, 2023: Dug a pit and found weak and unstable snow. We backtracked to the ridge. A recent avalanche from 2 days ago involved new, windblown snow.

Advisory Region
Bridger Range
Longitude
-110.94W
Latitude
45.79N
Avalanche Details: Large natural avalanche on Saddle Peak
Bridger Range, 2023-01-03