

A layer of near surface facets was found 40 cm's below the surface in the Flanders drainage up Hyalite.Ths layer produced unstable results in some stability tests but not all. It is not a major problem at the moment, but could become more reactive if stressed by a new load. Photo GNFAC

Advisory Region
Northern Gallatin

Forecast link: GNFAC Avalanche Advisory for Tue Feb 11, 2014GNFAC Avalanche Forecast for Wed Feb 12, 2014
Northern Gallatin, 2014-02-10